
Record player amplifier 22AF270/00B/00L





Free service manuals (iratis schema's

Digitized by

www.freeservicemanuals.info

Service Manual



Documentation Technique Servicio Dokumentation Documentazione di Servizio Huolte-Ohje Manual de Servicio Manual de Servicio



Subject to modification

4822 725 12583

Printed in The Netherlands

Digitized in Heiloo the Netherlands



CS 60 740

Not for sale!




Fig. 1



Safety regulations require that the set be restored to its original condition and that parts which are identical with those specified, be used.



Veiligheidsbepalingen vereisen, dat het apparaat bij reparatie in zijn oorspronkelijke toestand wordt teruggebracht en dat onderdelen, identiek aan de gespecificeerde, worden toegepast.



Les normes de sécurité exigent que l'appareil soit remis à l'état d'origine et que soient utilisées les pièces de rechange identiques à celles spécifiées.



Die Sicherheitsvorschriften erfordern, dass das Gerät sich nach der Reparatur in seinem originalen Zustand befindet und dass die benutzten Einzelteile den aufgeführten Teilen identisch sind.



Le norme di sicurezza esigono che l'apparecchio venga rimesso nelle condizioni originali e che siano utilizzati i pezzi di ricambio identici a quelli specificati.



Säkerhetsbestämmelserna kräver att varje reparation skall utföras korrekt med hänsyn till ursprunglig placering av komponenter, ledningar etc. och med användning af föreskrivna reservdelar.




Myndighedernes sikkerheds- og radiostøjbestemmelser kraever, at enhver reparation skal udføres korrekt m.h.t. overholdelse af originalplacering og montering af komponenter, ledningsbundter, etc., og ved anvendelse af de foreskrevne reservedele.



Sikkerhetsbestemmelser kreves at apparatet blir gjennopprettet til orignial utførelse og at deler som er identiske med de som er spesifisert, blir benyttet.



Korjatessa laitetta on turvallisuussyistä ehdottomasti eneteltävä oikein ja käytettävä tehtaan määräämiä alkuperäisvaraosia.






Fig. 2

-IC-			-R-	-		-S-			-Miscellaneous - Divers-	
IC401 IC451	TBA810SH TDA1059B	4822 209 80297 4822 209 80361	R503 R566	220 k Ω 100 Ω 120 Ω ± 2 % 220 Ω	4822 105 10326 4822 100 10234 5322 116 54426 4822 100 10235	S426 (98)	AD4085/X4	4822 240 40076	M458 (70) F462	4822 361 20148 4822 252 20007 4822 145,30108
-D-	+		R568 R569			- SK -		4822 290 80226 4822 290 80225 4822 492 40721	T468 (60)	
D474,475 D476	BY206 BAX18A	4822 130 30839 4822 130 31025				SK-K1 (74 SK-K2 (73 SK-J (97)				